



Views on the new vestibules. A new staircase in dark pickled oak, refering to the existing wooden elements of the building, was introduced to connect the second and the first floor.

Images ©Stijn Bollaert







The historic courtyard had been covered firstly in the 19th Century by introducing a new stained glass cupola. This invervention changed completely the circulation of the building. Toghether with that intervention the interiors of the Bel Etage were refurbished. At the end of the 20th century a second cupola was added (see picture on the right). The project removed this second cupola and restored the outer façades of the second level, showing to the courtyard. On the technical cupola an art intervention of Germaine Kruip was done. The glass panels reflect the sky and campanile and give artificial light in the evening towards the big staircase below the historic cupola.

Images above ©Kioni Papadopoulos Images beneath ©Stijn Bollaert



Antwerp City Hall - Origin & HUB 4